



Lower level meeting room accessed from rear of building and allowing ADA access.



Lower level settling with moisture damage



Moisture damaged fire door to be replaced



Heat pumps located in lower level with associated ductwork. 2 of the 3 pumps are inoperative.



The rear of the building where ADA access is available.



Stairway from lower level to main floor. The elevator is located to the right and behind the stair wall is the theatre.



The Widlund Gallery on the main level. There are rotating art and cultural exhibits presented monthly



The main street entrance as viewed from the Widlund Gallery



Interpretive panels, restrooms and public meeting rooms.



Rear entrance from Main Street



Street view from Main Street



What we hope to get back to once repairs are made.