LABOR AND MATERIALS	
Copper Connection	. <b>\$</b>
Curb Valve In.	
Service box Short 3½ x 4½ Cold returned Long 4½ x 5½	S
Ft. 34 in. Copper Pipe at	
Nipplesin, at	\$
Bushings to in. at	A STATE OF THE PROPERTY OF THE
Red'g Coupl'gs to in. at	
Union in, at	
Meter in, at	\$
	1,700
Compound Joints at	
Maintenance Foreman	,
Hrs. Water Maint. Man-1 at.	A second
Hrs. Water Maint. Man-2 at	
Hrs. Garage Foreman at	
Hrs. Labor— at	4
Hrs. Compressor at	. \$
Trucking	ş
Pav't Patch	
Tay t raten	
	. 7
Name - 1	\$
1	-
	<b>a</b>
(4)	

Tax ID # 309.16-6-2

ARLINGTO	V St.	 1	vo. 25
Name of Owner			
Labor and Mat'l. Report			1996
(*)			
*			
,			
	• Curb Box		
Main	© Curb Box  Elev. of  Main at ta	ıp	
DATE OF STREET WAS AND A STREET OF STREET	Elev. of	ıp	Gate at
DATE OF STREET WAS AND A STREET OF STREET	Elev. of	ıp	^
Main Gate at ●	Elev. of	•	
DATE OF STREET WAS AND A STREET OF STREET	Elev. of	•	
DATE OF STREET WAS AND A STREET OF STREET	Elev. of Main at ta	•	^
DATE OF STREET WAS AND A STREET OF STREET	Elev. of Main at ta	•	

LSM-5C-6-1-67