

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$ "	\$
1	Curb Valve F.S. & V.		} $\frac{3}{4}$ in.
1	Service box Old returned	{ Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ Buff or Rdway	
20	Ft. $\frac{3}{4}$ in.	{ Copper G.I. C.I. } Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs to in. at	\$
	Union		
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.	at \$ per C	\$
	Trucking		\$
	Pay't Patch		\$
	Tap by Giffard & Co.		\$
	7-18-58		\$
	O'head		\$

St. Pl. Ave. No. 20

Auburn

Name of Owner Mrs Bessie Wallace

Labor and Mat'l. Report July 18 19 58

● Curb Box

C.I. 1958  
6" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-SC-2-5 56