## LABOR AND MATERIALS

Copper Connection	<b>.</b> \$
Curb Cock Valve In	. <b>s</b>
Service box Old returned  Short 3½ x 4½ Long 4½ x 5½ Buff or Rdway  The state of th	
Gin Jan	Ψ
Nipplesin. at	\$
Bushings to in. at	. \$
Red'g   Coupl'gstoin. at	\$
Unionin, at	. \$
Meter in, at	. \$
Lead Joints at	. \$
Compound Joints at	\$
Maintenance Foreman	75. ·
Hrs. Water Maint. Man-1 at	
Hrs. Water Maint. Man-2 at	\$
Hrs. Garage Foreman at	. \$
Hrs. Laborat	. \$
Hrs. Compressor at	. \$
Compensation Ins. at \$per C	\$
Trucking	. \$
Pav't Patch	\$
	\$
***************************************	. \$
****	. \$
O'head	<u> </u>
	\$

	St. 14
3ALDWIN	Ave. No. /
ime of Owner	12 40
16 TAX ID # 302.12-	13-40
bor and Mat'l. Report	19
S R	576 9" • Curb Box
6" Main	Elev. of Main at tap
Gate at •	• Gate
	Curb Box