

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4		\$
1	Curb	Cock Valve T. S. & V.	3/4 in.		\$
1	Service box - Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway			\$
25	Ft. 3/4 in.	Copper C.I. C.I.	Pipe at		\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins. at \$	per C			\$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
	O'head				\$
					\$

St. _____
 Pl. _____
 Ave. No. 173

BAY-

Name of Owner _____

TAX ID # 302.12-26-7

Labor and Mat'l. Report 19

SERRELLA

● Curb Box

Gate at ●

Elev. of
Main at tap _____

● Gate at

● Curb Box

LSM-5C-6-1-67