

LABOR AND MATERIALS

1 Copper } Connection ^{3/4} \$ _____
 Lead }
 1 Curb } Cock Valve } ^{3/4} in. \$ _____
 T.S. & V. }
 1 Service box } Short 3 1/2 x 4 1/2 }
 Old returned } Long 4 1/2 x 5 1/2 } \$ _____
 2 1/2 Ft. ^{3/4} in. { Copper } Pipe at \$ _____
 { C.I. }
 { C.I. }
 Nipples in. at \$ _____
 Bushings to in. at \$ _____
 Red'g }
 Inc'g } Coupl'gs to in. at \$ _____
 Union in. at \$ _____
 Meter in. at \$ _____
 \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman at \$ _____
 Hrs. Labor at \$ _____
 Hrs. Compressor at \$ _____
 \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
 \$ _____
 \$ _____
 \$ _____
 \$ _____

BAY

St. _____
 Pl. _____
 Ave. No. 209

Name of Owner _____

TAX ID # 302.12-10-16

Labor and Mat'l. Report

July 19 27



23 1/2" 18 1/2"

● Curb Box

TERRA COTTA

6" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

● Curb Box

TAP ON TERRA COTTA