

### Labor and Materials

Copper	}	Connection.....	\$	
Lead				
Curb	{	Cock Valve	.....in	\$
		T. S. & V.		
Service Box	{	Short 3 1/2 x 4 1/2	} .....	\$
Old returned		Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
8 1/2 Ft.	3/4 in.	Copper	} Pipe at .....	\$
		Galv-iron		
		Cast-iron		
Nipples	.....in. at		\$	
Bushings	.....to .....	.....in. at	\$	
Red'g	{	Conplings.....to .....	in. at	\$
Inc'g				
Union	.....in. at		\$	
Meter	.....in. at		\$	
Lead Joints	at		\$	
Leadite Joints	at		\$	
Hrs. Foreman	at		\$	
Hrs. Chauffeur	at		\$	
Hrs. Tapper	at		\$	
Hrs. Labor	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins.			\$	
Trucking			\$	
Builders Use of Water			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. Bay  
~~St.~~  
 Ave. No. 88

---

Name of Owner J.W. Hamilton

---

Labor and Mat'l. Report 4/20/2019

---

---

4" STEEL  
 4" Main Union St. Elev. of Main at tap.....

Gate at • Gate at

---

● Curb Box

NEW COPPER SERVICE

SEPT. 2000