

LABOR AND MATERIALS

_____	Copper } Connection	_____	\$
_____	Lead } _____	_____	\$
_____	Curb } Cock	_____	\$
_____	} Valve	_____	\$
_____	} T.S. & V.	_____	\$
_____	Service box { Short 3-1/2 x 4-1/2	_____	\$
_____	Old returned { Long 4-1/2 x 5-1/2	_____	\$
46.3	Ft. 3/4 in. { Copper	_____	\$
	} G.I.	_____	\$
	} C.I.	_____	\$
_____	Nipples _____ in. at	_____	\$
_____	Bushings _____ to _____ in. at	_____	\$
_____	Red'g _____	_____	\$
_____	Inc'g _____	_____	\$
_____	Union _____ in. at	_____	\$
_____	Meter _____ in. at	_____	\$
_____	_____	_____	\$
_____	Compound Joints at	_____	\$
_____	Maintenance Foreman _____	_____	\$
_____	Hrs. Water Maint. Man - 1 at	_____	\$
_____	Hrs. Water Maint. Man - 2 at	_____	\$
_____	Hrs. Garage Foreman _____ at	_____	\$
_____	Hrs. Labor _____ at	_____	\$
_____	Hrs. Compressor at	_____	\$
_____	_____	_____	\$
_____	Trucking _____	_____	\$
_____	Pav't Patch _____	_____	\$
_____	_____	_____	\$
_____	_____	_____	\$
_____	_____	_____	\$
_____	_____	_____	\$

BOYLSTON

St. Pl. Ave. No. 39

Name of Owner _____

Labor and Mat'l. Report 19 _____

