

LABOR AND MATERIALS

1	Copper	} Connection <sup>3/4"</sup>	\$
	Lead		
1	Curb	} Cock Valve } <sup>3/4"</sup> in.	\$
			T.S. & V.
1	Service box		} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }
	Old returned		
23	Ft. <sup>3/4"</sup> in.	{ Copper } Pipe at	\$
		{ <del>C.I.</del> }	
		{ <del>C.I.</del> }	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1 at		\$
	Hrs. Water Maint. Man—2 at		\$
	Hrs. Garage Foreman at		\$
	Hrs. Labor— at		\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

CAMERON <sup>St.</sup> 9  
<sup>Pt.</sup> Ave. No.

Name of Owner  
TAX ID # 302.12-13-65

Labor and Mat'l. Report 19.27



● Curb Box

<sup>4"</sup> Main Elev. of Main at tap <sup>4'</sup>  
Gate at ● ● Gate at

● Curb Box

20' 0" 22' 10"