

LABOR AND MATERIALS

1	Copper Lead	} Connection ^{3/4"}	\$
1	Curb		} Cock Valve } ^{3/4"} in.
		T.S. & V.	
1	Service box Old returned	} Short ^{3 1/2} x ^{4 1/2} } Long ^{4 1/2} x ^{5 1/2} }	\$
11	Ft. ^{3/4"} in.		} Copper } } C.I. } } C.I. }
		Pipe at	
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. CHARLOTTE
 Ave. No. 11

Name of Owner _____

Labor and Mat'l. Report JULY 19 34



● Curb Box

4" Main

Elev. of Main at tap 5 1/2'

Gate at ● ● Gate at

TAX ID # 302.20-7-14

● Curb Box