

## LABOR AND MATERIALS

1	Copper	Connection	<i>3/4"</i>		\$
1	Curb	Cock Valve	<i>3/4"</i>	in.	\$
		(T. S. & V.)			
1	Service box	Short <i>3 1/2</i> X <i>4 1/2</i>			\$
	Old returned	Long <i>4 1/2</i> X <i>5 1/2</i>			\$
		Buff or Rdway			
10	Ft.	<i>3/4"</i> in.	Copper	Pipe at	\$
			C. I.		
	Nipples	..... in. at			\$
	Bushings	..... to ..... in. at			\$
	Red'g				
	Inc'g	Coupl'gs ..... to ..... in. at			\$
	Union	..... in. at			\$
	Meter	..... in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Labor	..... at			\$
	Hrs. Labor	..... at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$ ..... per C			\$
	Trucking				\$
	Pav't Patch				\$
	<i>Tap by Miller Aug 13-47</i>				\$
	O'head				\$
					\$

	St.	<i>68</i>
<i>Cherry</i>	<del>Pr.</del>	
	Ave. No.	<i>54</i>
Name of Owner		
<i>O. Leary</i>		
Labor and Mat'l. Report		
<i>Aug 13</i>	19	<i>47</i>
● Curb Box		
<i>4"</i>	Main	Elev. of Main at tap <i>5 1/2"</i>
Gate at ●		● Gate at
● Curb Box		