

Labor and Materials

1	Copper } Connection <i>3/4"</i>	\$ 3.20
1	Curb } Cock Valve } <i>3/4"</i> in.	\$ 1.00
1	Service Box } Short <i>3 1/2 x 4 1/2</i>	\$ 1.30
	Old returned } Long <i>4 1/2 x 5 1/2</i>	
2.4	Pt. <i>3/4"</i> in. } Copper Galv. Iron } Pipe at.	\$ 52.8
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
1	Red <i>3/4"</i> } Couplings, <i>3/4"</i> to <i>1"</i> in. at.	\$ 1.15
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick } Mack } at	\$
	} Red } at	
	} Asphalt }	\$
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
4	Hrs. Foreman at..... <i>6.25</i>	\$ 2.50
6	Hrs. Common Labor at..... <i>50</i>	\$ 3.00
	Hrs. Common Labor at.....	\$
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ <i>1.15</i>
<i>yes</i>	Trucking.....	\$ <i>1.00</i>
<i>yes</i>	Builders' Use of Water.....	\$
	Total <i>17.58</i>	

27-15 *61*

Labor and Material Report *Apr 14* 1927

3/4" tap at 45' horizontal



Main Elev. of Main at tap *511*

Gate at ● Gate at ●

● Curb Box

New Tap

This place razed
shot off at curb
11-11-60.