

LABOR AND MATERIALS

Copper	} Connection	-----	\$
Lead		-----	\$
Curb	} Cock Valve T. S. & V.	----- in.	\$
Service Box		-----	\$
Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$
Ft. ----- in.		} Copper Galv Iron Cast Iron	Pipe at ----- \$
Nipples ----- in. at -----			
Bushings ----- to ----- in. at -----		\$	
Red'g } Couplings ----- to ----- in. at -----		\$	
Inc'g }		\$	
Union ----- in. at -----		\$	
Meter ----- in. at -----		\$	
Lead Joints at -----		\$	
Leadite Joints at -----		\$	
Hrs. Foreman at -----		\$	
Hrs. Chauffeur at -----		\$	
Hrs. Tapper at -----		\$	
Hrs. Labor at -----		\$	
Hrs. Labor at -----		\$	
Hrs. Compressor at -----		\$	
Compensation Ins. -----		\$	
Trucking -----		\$	
Builders Use of Water -----		\$	
-----		\$	
-----		\$	
-----		\$	
-----		\$	

St. **21-25**
 Pt. -----
 Ave. No. **53**

Cooper

Name of Owner
TAX ID # 303.17-13-9

Labor and Mat'l. Report 19 **12**

Main Elev. of Main at tap

Gate at ● ● Gate at

● Curb Box

↳ **Buffalo Box**

This Tap Shut off

At Curb 6-15-1972