

LABOR AND MATERIALS

1	Copper Lead	} Connection	\$	
	Curb	{ Cock Valve T. S. & V. } in.	\$	
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway }	\$	
6	Ft. 1/2	{ Copper Galv Iron Cast Iron }	Pipe at	\$	
	Nipples in. at		\$	
	Bushings to	in. at	\$	
	Red'g Inc'g	} Couplings to	\$	
	Union in. at		\$	
	Meter in. at		\$	
	Lead Joints at			\$	
	Leadite Joints at			\$	
	Hrs. Foreman at			\$	
	Hrs. Chauffeur at			\$	
	Hrs. Tapper at			\$	
	Hrs. Labor at			\$	
	Hrs. Labor at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins.			\$	
	Trucking			\$	
	Builders Use of Water			\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

St. _____
 Pt. _____
 Ave. No. 1

Cortland

Name of Owner _____

TAP MADE 025, 1, 1915

Labor and Mat'l. Report SEP '6 - 1939 19

● Curb Box

..... Main
Elev. of
Main at tap.....

Gate at ●
● Gate at

6' to min

● Curb Box

GALV.