

### LABOR AND MATERIALS

1	Copper <del>Lead</del>	Connection $\frac{3}{4}$			\$
1	Curb	Cock Valve T. S. & V.	$\frac{3}{4}$ in.		\$
1	Service box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$			\$
31' <sup>4#</sup>		Copper	Pipe at		\$
		<del>C.I.</del> C.I.			\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
					\$
					\$

DARWIN

~~St.~~  
~~Pl.~~

Ave. No. 9

Name of Owner

Labor and Mat'l. Report

OCT. 6 1934



13-7    20-5

● Curb Box

4" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD TAP SHUT OFF AT MAIN