LABOR AND MATERIALS

Copper Connection	\$
Curb Cock in. Service box Short 3½ x 4½	\$
Old returned \ Long 41/2 x 51/2 \	\$
1 Ft. 7 in. Copper G. I. Pipe at	\$
Nipplesin. at	
Bushings to in, at	
Red'g Coupl'gs to in. at	_ \$
Inc'g Coupl'gstoin. at	\$
Unionin, at	S
Meter in, at	\$
Compound Joints at	
Maintenance Foreman	
Hrs. Water Maint. Man—1 at	
Hrs. Water Maint. Man—2 at	
Hrs. Garage Foreman at	
Hrs. Labor—at	
Hrs. Compressor at	
Tanakina	\$
Trucking	- \$
Pav't Patch	<u> </u>
**)	- \$
B	- \$
	_ \$
	- <u>\$</u>
	\$

Dough	AS Ave. No. 7
Name of Owner	
CHAS. HOL	LAND
Labor and Mat'l. Report	JULY 26 1921
	19-5 26-4
	● Curb Box
/2 "Main	Elev. of Main at tap
Gate at •	• Gate at
	• Curb Box

LSM-5C-6-1-6