Labor and Mater	iala
Labor and Mater	Tais
Connection 2	
Lead Connection	\$
Curb Cock	s
(T. S. & V.)	
Service Box Short 3½ x 4½	
Old returned Long 4 2 5 1/2 Buff. or Rdway	 \$
Ft. Gale Ison	
-Control Pipe at .	 \$
Nipples in. at	
Bushings	1962221111111111111
Inc'g Conplingstoin.	at
Unionin. at	
Meter in at	······ \$
Lead Joints at	\$
Leadite Joints at	\$
Hrs. Foreman at Hrs. Chauffeur at	
Hrs. Tapper at	
Hrs. Labor at	
Hrs. Labor at	\$
Compressor at	·····\$
Compensation Ins	
Builders Use of Water	···········\$ ········
	4
¥1	······ \$
	\$

Donals i	Pt. Ave. No
Name of Owner	berte
Labor and Mat'l. Report	June 14 19 3
	5
	Curb Box
12 "Main	Elev. of Main at tap
Gate at •	• Gate at
	Curb Box

LABOR AND MATERIALS

Copper Connection	\$	
Curb \ Cock \ Valve \ \ in		
T.S. & V. J Service box Short 3-1/2 x 4-1/2 Old returned Long 4-1/2 x 5-1/2	\$	
\dots Ft. \dots in. $\left\{ egin{array}{ll} Copper \\ G.l. \\ C.l. \end{array} \right\}$ Pipe at \dots		
Nipples in. at	\$	
Bushings to in. at	\$	
Red'g		
Inc'g		
Union in. at	\$	
Meter in. at	\$	
X	\$	
Compound Joints at	\$	
Maintenance Foreman \$		
Hrs. Water Maint. Man - 1 at \$		
Hrs. Water Maint. Man - 2 at \$		
Hrs. Garage Foreman at \$		
Hrs. Labor at \$		
Hrs. Compressor at	\$	
1 	\$	
Trucking	\$	
Pav't Patch	\$	
10	\$	
(<u> </u>	\$	
) N	\$	
7====477=========	\$	
	\$	

Doy6LAS Name of Owner	St. 15	
Labor and Mat'l. Report 1	9	
A=24/ A POACH POACH Curb Box		
Main	Elev. of Main at tap	
Gate at • 7 FA	ST OF Gate at	
MATER 1	Curb Box	