

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$ 2.76
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$ 3.49
1	Service Box Old returned	Short 3 1/2 x 4 1/2		\$ 4.74
		Long 4 1/2 x 5 1/2	Buffer Rdway	
7	Ft.	3/4" in.	Copper Galv Iron Cast Iron	38 2.66
	Nipplesin. at		\$
	Bushingsto.....in. at		\$
	Red'g Inc'g	Couplings.....to.....in. at		\$
	Unionin. at		\$
	Meterin. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Chauffeur	at		\$
6	Hrs. Tapper	at	124	\$ 7.44
6	Hrs. Labor	at	113	\$ 6.78
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	4406		\$ 6.3
	Trucking			\$ 1.00
	Builders Use of Water			\$ 15.96
	Tap by Gissard	4-9-53		\$
				\$
				\$
				\$
				\$ 45.46

29.50

39-53

St. 14
Pl. 9
Fredella Ave. No. 9

Name of Owner
Louis Di Leone

Labor and Mat'l. Report April 9 1953

Concrete Platform

6" Main

Elev. of Main at tap 5'

Gate at ● Gate at ●

TAX ID # 310.5-4-7

● Curb Box

This Tap made to repair leak.

19' 4" 15' 5"