

LABOR AND MATERIALS

<u>1</u>	Copper } Connection _____ \$ _____
<u>1</u>	Lead } Curb } Cock } _____ in. \$ _____
	Valve } _____
	_____ } _____
<u>1</u>	Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____
	Old returned { Long 4-1/2 x 5-1/2 } _____
<u>22</u>	Ft. <u>3/4</u> in. { Copper } Pipe at _____ \$ _____
	_____ } _____
	_____ } _____
	Nipples _____ in. at _____ \$ _____
<u>1</u>	Bushings <u>3/4</u> to <u>1/2</u> in. at _____ \$ _____
	Red'g _____ \$ _____
	Inc'g _____ \$ _____
	Union _____ in. at _____ \$ _____
	Meter _____ in. at _____ \$ _____
	_____ \$ _____
	Compound Joints at _____ \$ _____
	Maintenance Foreman _____ \$ _____
	Hrs. Water Maint. Man - 1 at _____ \$ _____
	Hrs. Water Maint. Man - 2 at _____ \$ _____
	Hrs. Garage Foreman _____ at _____ \$ _____
	Hrs. Labor _____ at _____ \$ _____
	Hrs. Compressor at _____ \$ _____
	_____ \$ _____
	Trucking _____ \$ _____
	Pav't Patch _____ \$ _____
	_____ \$ _____
	_____ \$ _____
	_____ \$ _____
	_____ \$ _____
	_____ \$ _____
	_____ \$ _____

St. GARFIELD
 Ave. No. 20

Name of Owner _____
 TAX ID # 302.19-18-5

Labor and Mat'l. Report 1931, APR. 24



27'9" 32'10"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

22' to main

● Curb Box

OLD TAP DISCONNECTED