

St. Arbor Dr.  
 Pt. 39  
 Ave. No. 39

Name of Owner Bishop

Labor and Mat'l. Report Jan. 24 1956

6" Main      Elev. of Main at tap 5 1/2'  
 Gate at ●      ● Gate at

● Curb Box

L M-5C-2-1-54

### LABOR AND MATERIALS

1 Copper Lead	Connection <u>3/4"</u>	\$ <u>2.71</u>
1 Curb	Cock Valve T.S. & V. <u>3/4 in.</u>	\$ <u>3.83</u>
1 Service box - Old returned	Short <u>3 1/2 x 4 1/2</u> Long <u>4 1/2 x 5 1/2</u> Buff or Rdway	\$ <u>4.69</u>
10 Ft. <u>3/4 in.</u>	Copper G.I. Pipe at <u>45</u>	\$ <u>4.50</u>
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g Inc'g } Coupl'gs	to in. at	\$
Union	in. at	\$
Meter	in. at	\$
Lead Joints at		\$
Compound Joints at		\$
2 Maintenance Foreman	<u>1.51</u>	\$ <u>3.07</u>
Hrs. Water Maint. Man-1 at		\$
5 Hrs. Water Maint. Man-2 at	<u>1.24</u>	\$ <u>6.20</u>
Hrs. Garage Foreman at		\$
10 Hrs. Labor at	<u>1.13</u>	\$ <u>11.73</u>
Hrs. Compressor at		\$
Compensation Ins. at	\$ <u>56.86</u> per C.	\$ <u>1.16</u>
Trucking		\$ <u>1.50</u>
Pav't Patch		\$ <u>17.92</u>
<u>Tap by Gifford - 24-56</u>		
O'head		\$
		\$ <u>56.66</u>