

### LABOR AND MATERIALS

1	<del>Lead</del> Copper	Connection	<u>3/4</u>		\$
1	Curb	Cock Valve T.S. & V.	} <u>3/4</u> in.		\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway			\$
18	Ft.	Copper <del>C.I.</del> C.I.	} Pipe at		\$
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Coupl'gs	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Maintenance Foreman				\$
	Hrs. Water Maint. Man-1	at			\$
	Hrs. Water Maint. Man-2	at			\$
	Hrs. Garage Foreman	at			\$
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.	at \$ per C			\$
	Trucking				\$
	Pav't Patch				\$
					\$
					\$
					\$
	O'head				\$
					\$

St. BAZ DWIN  
Pt. Ave. No. 45

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report 19 81

# 45

● Curb Box

6 Main Elev. of Main at tap 5

Gate at ● ● Gate at

18' to main

