

LABOR AND MATERIALS

1 Copper } Connection ^{3/4"} \$ _____
 Lead }
 1 Curb } Cock } 3/4 in. \$ _____
 } Valve }
 } T. S. & V. }
 1 Service box } Short 3 1/2 x 4 1/2 }
 Old returned } Long 4 1/2 x 5 1/2 } \$ _____
 } Buff or Rdway }
 12 Ft. ^{3/4} in. } Copper } Pipe at \$ _____
 } G. I. }
 } G. I. }
 Nipples _____ in. at \$ _____
 Bushings _____ to _____ in. at \$ _____
 Red'g }
 Inc'g } Coupl'gs _____ to _____ in. at \$ _____
 Union _____ in. at \$ _____
 Meter _____ in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman _____ at \$ _____
 Hrs. Labor _____ at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
 Tap by Gifford & Co. \$ _____
 9-29-60. \$ _____
 O'head \$ _____
 \$ _____

St. _____
 Pl. _____
 Ave. No. 65

Bay
 Name of Owner Anthony Jones.

Labor and Mat'l. Report Sept. 29 1960

28'9" 22'5"

● Curb Box

10" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

old 1/2" Tap
 Disconnected at
 main.

LSM-5C-2-5 56