

LABOR AND MATERIALS

1	Copper	} Connection <u>3/4</u>	\$
	Lead		
1	Curb	} <u>3/4</u> in.	\$
	Cock		
	Valve		
		T.S. & V.	
1	Service box	} <u>Short 3 1/2 x 4 1/2</u>	\$
	Old returned		<u>Long 4 1/2 x 5 1/2</u>
			<u>Buff or Rdway</u>
36	Ft. <u>3/4</u> in.	} Copper	\$
			G.I.
			G.I.
		Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g	} Coupl'gs to in. at	\$
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor—	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins. at \$	per C	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
	O'head		\$
			\$

St.
Pl.
Ave. No. 108

BAK

Name of Owner _____
TAX ID # 302.16-19-4

Labor and Mat'l. Report 19

● Curb Box

10 Main Elev. of Main at tap 5

Gate at ● ● Gate at

● Curb Box

L.S.M.—5C—6-1-67