

LABOR AND MATERIALS

<u>Copper</u> <u>Lead</u>	Connection	_____	\$	_____
Curb	Cock Valve T.S. & V.	} _____ in.	\$	_____
	Old returned	{ Long 4-1/2 x 5-1/2 }		
<u>20</u>	<u>3/4</u> in.	{ Copper G.I. C.I. }	Pipe at	_____ \$ _____
_____	Nipples	_____ in.	at	_____ \$ _____
_____	Bushings	_____ to _____ in.	at	_____ \$ _____
_____	Red'g			
_____	Inc'g			
_____	Union	_____ in.	at	_____ \$ _____
_____	Meter	_____ in.	at	_____ \$ _____
_____	Compound Joints	at		_____ \$ _____
_____	Maintenance Foreman			_____ \$ _____
_____	Hrs. Water Maint. Man - 1	at		_____ \$ _____
_____	Hrs. Water Maint. Man - 2	at		_____ \$ _____
_____	Hrs. Garage Foreman	at		_____ \$ _____
_____	Hrs. Labor	at		_____ \$ _____
_____	Hrs. Compressor	at		_____ \$ _____
_____	Trucking			_____ \$ _____
_____	Pav't Patch			_____ \$ _____
_____				_____ \$ _____
_____				_____ \$ _____
_____				_____ \$ _____
_____				_____ \$ _____

E BEACON St.
Pl. Ave. No. 41

Name of Owner _____

Labor and Mat'l. Report # 12/5/06

● Curb Box

6" Main

Elev. of Main at tap 6 1/2

Gate at ●

● Gate at

water ● Curb Box
TAP ON FABSON
SEWER TAP ON
E. BEACON