

LABOR AND MATERIALS

2' Copper } Connection 15' PLASTIC
 Lead }
 Curb } Cock }
 Valve } in. } \$
 T.S. & V. }
 Service box { Short 3-1/2 x 4-1/2 } \$
 Old returned { Long 4-1/2 x 5-1/2 } \$
 (17) Ft. (TL) in. { Copper } Pipe at \$
 G.I. }
 Gal. }
 Nipples 45' PLASTIC in. at + 2' COPPER \$
 Bushings _____ to _____ in. at \$
 Red'g _____ \$
 Inc'g _____ 9/5/17 \$
 Union _____ in. at \$
 Meter _____ in. at \$
 _____ \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man - 1 at \$
 Hrs. Water Maint. Man - 2 at \$
 Hrs. Garage Foreman _____ at \$
 Hrs. Labor _____ at \$
 Hrs. Compressor at \$
 _____ \$
 Trucking _____ \$
 Pav't Patch _____ \$
 _____ \$
 _____ \$
 _____ \$
 _____ \$
 _____ \$

E BEACON St. Ave. No. 45
 Name of Owner GILLIS, MARY L.
 Labor and Mat'l. Report 19 9/5/17

● Curb Box
 6" Main Elev. of Main at tap 6'
 Gate at ● Gate at

● Curb Box
 NEW MAIN 6"
 NEW TAP
 15' COPPER 2' PLASTIC