

LABOR AND MATERIALS

1 Copper } Connection  $\frac{3}{4}$ " \$ \_\_\_\_\_  
 Lead }  
 1 Curb } Cock Valve }  $\frac{3}{4}$ " in. \$ \_\_\_\_\_  
 T.S. & V. }  
 1 Service box } Short  $3\frac{1}{2} \times 4\frac{1}{2}$  }  
 Old returned } Long  $4\frac{1}{2} \times 5\frac{1}{2}$  } \$ \_\_\_\_\_  
 15 Ft.  $\frac{3}{4}$ " in. } Copper } Pipe at \$ \_\_\_\_\_  
 } G.I. }  
 } G.I. }  
 Nipples in. at \$ \_\_\_\_\_  
 Bushings to in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs to in. at \$ \_\_\_\_\_  
 Union in. at \$ \_\_\_\_\_  
 Meter in. at \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman at \$ \_\_\_\_\_  
 Hrs. Labor— at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 \$ \_\_\_\_\_  
 \$ \_\_\_\_\_

BROAD

St. ~~Pl.~~ Ave. No. 99

Name of Owner \_\_\_\_\_  
 TAX ID # 309.35-1-2

Labor and Mat'l. Report AUG 19 26



42'4" 28'6"

● Curb Box

6" Main Elev. of Main at tap 6'  
 Gate at ● ● Gate at

● Curb Box