

### LABOR AND MATERIALS

1	Copper	}	Connection	1/2"	\$	
	Lead					
1	Curb	}	Cock Valve T.S. & V.	3/4" in.	\$	
1	Service box Old returned			}	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway.	\$
37	Ft. 3/4" in.					}
			Pipe at	\$		
	Nipples		in. at	\$		
	Bushings		to in. at	\$		
	Red'g Inc'g	}	Coupl'gs	to in. at	\$	
	Union			in. at	\$	
	Meter		in. at	\$		
	Lead Joints at			\$		
	Compound Joints at			\$		
3	Hrs. Water Maint. Man—1		at	\$		
	Hrs. Water Maint. Man—2		at	\$		
4	Hrs. Labor		at	\$		
	Hrs. Labor		at	\$		
	Hrs. Compressor at			\$		
	Compensation Ins. at \$		per C.	\$		
	Trucking			\$		
	Pav't Patch			\$		
				\$		
				\$		
				\$		
				\$		
	O'head			\$ 14.84		

St. 140  
 Pl. 108  
 Ave. No. 108

Broad

---

Name of Owner  
Curtis Traver

---

Labor and Mat'l. Report Aug 21 19 23

---

● Curb Box

---

6" Main Elev. of Main at tap 6"

Gate at ● ● Gate at

---

● Curb Box

Duplicate Copy.

LSM-5C 10-21-49