

LABOR AND MATERIALS

Copper } Connection	_____	\$ _____
Lead } _____	_____	\$ _____
Curb } Cock	_____ in.	\$ _____
} Valve	_____	\$ _____
} T. S. & V.	_____	\$ _____
Service box } Short 3½ x 4½	_____	\$ _____
Old returned } Long 4½ x 5½	_____	\$ _____
} Buff or Rdway	_____	\$ _____
Ft. _____ in. } Copper	_____ Pipe at _____	\$ _____
} G. I.	_____	\$ _____
} C. I.	_____	\$ _____
Nipples _____ in. at _____	_____	\$ _____
Bushings _____ to _____ in. at _____	_____	\$ _____
Red'g } Coupl'gs _____ to _____ in. at _____	_____	\$ _____
Inc'g } _____	_____	\$ _____
Union _____ in. at _____	_____	\$ _____
Meter _____ in. at _____	_____	\$ _____
Lead Joints at _____	_____	\$ _____
Compound Joints at _____	_____	\$ _____
Maintenance Foreman _____	_____	\$ _____
Hrs. Water Maint. Man—1 at _____	_____	\$ _____
Hrs. Water Maint. Man—2 at _____	_____	\$ _____
Hrs. Garage Foreman _____ at _____	_____	\$ _____
Hrs. Labor— _____ at _____	_____	\$ _____
Hrs. Compressor at _____	_____	\$ _____
Compensation Ins. at \$ _____ per C. _____	_____	\$ _____
Trucking _____	_____	\$ _____
Pav't Patch _____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
_____	_____	\$ _____
O'head _____	_____	\$ _____
_____	_____	\$ _____

St. _____
Pl. _____

Carlton Court Ave. No. 2

Name of Owner CORNER LA ROSE ST.
DUNN + STEVENSON

Labor and Mat'l. Report Nov. 9 1955

La Rose St.

Tap ON CARLTON COURT,

_____ Main Elev. of Main at tap _____

Gate at • • Gate at •

TAX ID # 309.7-10-14

• Curb Box

L M-5C-2-1-54