

Labor and Materials

Copper	}	Connection.....	\$
Lead			
Curb	}	Cock	in \$
		Valve	
		T. S. & V.	
Service Box	}	Short 3½ x 4½	} \$
Old returned		Long 4½ x 5½	
		Buff. or Rdway	
Ft. in.	}	Copper	} Pipe at \$
		Galv Iron	
		Cast Iron	
Nipples	in. at		\$
Bushings	to	in. at	\$
Red'g	}	Conplings.....	to in. at \$
Inc'g			
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Leadite Joints	at		\$
Hrs. Foreman	at		\$
Hrs. Chauffeur	at		\$
Hrs. Tapper	at		\$
Hrs. Labor	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
Compensation Ins.			\$
Trucking			\$
Builders Use of Water			\$
			\$
			\$
			\$
			\$
			\$

11 Church St. ?

St.
Pl.
Ave. No.

Church St

Name of Owner
Fr. Gilligan - 141st Back of
"A C Warren St

Labor and Mat'l. Report *April 30* 1937

Need School

● Curb Box

av Church St
old connection ¾ Pipe
 Elev. of
 Main *Below Road* Main at tap.....

Gate at ● ● Gate at

● Curb Box