

LABOR AND MATERIALS

1	Copper Lead	} Connection <u>3/4</u>	\$
1	Curb		} Cock Valve F.S. & V. } <u>3/4</u> in.
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$	
12	Ft. <u>3/4</u> in.		} Copper C.I. C.I.
	Nipples	in. at \$	
	Bushings	to in. at \$	
	Red'g Inc'g	} Coupl'gs	to in. at \$
	Union		
	Meter	in. at \$	
	Compound Joints	at \$	
	Maintenance Foreman	\$	
	Hrs. Water Maint. Man-1	at \$	
	Hrs. Water Maint. Man-2	at \$	
	Hrs. Garage Foreman	at \$	
	Hrs. Labor	at \$	
	Hrs. Compressor	at \$	
	Trucking	\$	
	Pav't Patch	\$	
		\$	
		\$	
		\$	
		\$	

St. COOLIDGE  
 Ave. No. 19  
 Name of Owner  
ELIZABETH EGAN

Labor and Mat'l. Report JULY 13 1937



● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

● Curb Box

OLD SHUT OFF