

LABOR AND MATERIALS

1 Copper Lead } Connection	$\frac{3}{4}$		\$ 1.35	
1 Curb } Cock Valve T. S. & V. }	$\frac{3}{4}$ in.		\$ 1.80	
1 Service Box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buffer Rdway }		\$ 1.70	
25 Ft. $\frac{3}{4}$ in.		} Copper Galv Iron Cast Iron }	Pipe at 18	\$ 4.50
Nipples in. at				\$
Bushings to in. at			\$	
Red'g } Couplings to in. at			\$	
Inc'g			\$	
Union in. at			\$	
Meter in. at			\$	
Lead Joints at			\$	
Leadite Joints at			\$	
Hrs. Foreman at			\$	
3 Hrs. Chauffeur at	6.21x		\$ 1.87	
7 Hrs. Tapper at			\$ 5.00	
8 Hrs. Labor at	4.5		\$ 3.60	
Hrs. Labor at			\$	
1 Hrs. Compressor at	6.21x		\$.63	
Compensation Ins.			\$	
Trucking			\$ 3.00	
Builders Use of Water	Patch		\$ 5.00	
Taply Hessel			\$	
			\$	
			\$	
			\$	
			\$	
			\$ 26.77	

7 4 1941

St. 91
Pt.
Ave. No. 67

Cooper

Name of Owner

Garzia

Labor and Mat'l. Report July 7 1941



4 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

● Curb Box

REPLACED CURB BOX - AUG.
2000

TAX ID # 303.13-10-19