

LABOR AND MATERIALS

Copper	}	Connection	\$	
Lead			\$	
Curb	}	Cock Valve in.	\$	
		T. S. & V.	\$	
Service box	}	Short 3½x4½	\$	
Old returned		Long 4½x5½		
		Buff or Rdway		
Ft.	in.	}	Pipe at	\$	
					Copper
		G. I.			
		C. I.			
Nipples	in. at			\$	
Bushings	to	in. at		\$	
Red'g	}	Coupl'gs	to	in. at	\$
Inc'g					
Union	in. at			\$	
Meter	in. at			\$	
Lead Joints	at			\$	
Compound Joints	at			\$	
Hrs. Water Maint. Man—1	at			\$	
Hrs. Water Maint. Man—2	at			\$	
Hrs. Labor—	at			\$	
Hrs. Labor—	at			\$	
Hrs. Compressor	at			\$	
Compensation Ins. at \$	per C.			\$	
Trucking				\$	
Pav't Patch				\$	
				\$	
				\$	
				\$	
O'head				\$	
				\$	

Cortland

St. ~~Pl.~~
Ave. No. 27

Name of Owner

MEASURE IN CARD 8-15-51

Labor and Mat'l. Report

19



● Curb Box

Main

Elev. of
Main at tap

Gate at ●

● Gate at

● Curb Box