

### LABOR AND MATERIALS

Copper	}	Connection		\$
Lead				
Curb	}	Cock Valve T. S. & V.		in. \$
Service Box				
Old returned	}	Short 3 1/2 x 4 1/2		\$
		Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
Ft. $\frac{3}{4}$	}	Copper		Pipe at \$
		<del>Galv. Iron</del>		
		<del>Cast Iron</del>		
Nipples		in. at		\$
Bushings		to in. at		\$
Red'g Inc'g	}	Couplings		in. at \$
Union				
Meter		in. at		\$
Lead Joints		at		\$
Leadite Joints		at		\$
Hrs. Foreman		at		\$
Hrs. Chauffeur		at		\$
Hrs. Tapper		at		\$
Hrs. Labor		at		\$
Hrs. Labor		at		\$
Hrs. Compressor		at		\$
Compensation Ins.				\$
Trucking				\$
Builders Use of Water				\$
				\$
				\$
				\$
				\$

St.

Pl.

*Crandall*

Ave. No. *80*

Name of Owner

Labor and Mat'l. Report

19*12*



Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

RENEWAL TAP - 1927