

### LABOR AND MATERIALS

Copper	} Connection	-----	\$
Lead		-----	
Curb	} Cock Valve T. S. & V.	-----	in. ----- \$
Service Box		-----	
Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$
		-----	
		-----	
Ft. <u>3</u>	} Copper Galv-iron Cast-iron	-----	Pipe at ----- \$
in.		-----	
Nipples	-----	in. at -----	\$
Bushings	-----	to ----- in. at -----	\$
Red'g Inc'g	} Couplings	-----	to ----- in. at -----
		-----	
Union	-----	in. at -----	\$
Meter	-----	in. at -----	\$
Lead Joints	-----	at -----	\$
Leadite Joints	-----	at -----	\$
Hrs. Foreman	-----	at -----	\$
Hrs. Chauffeur	-----	at -----	\$
Hrs. Tapper	-----	at -----	\$
Hrs. Labor	-----	at -----	\$
Hrs. Labor	-----	at -----	\$
Hrs. Compressor	-----	at -----	\$
Compensation Ins.	-----		\$
Trucking	-----		\$
Builders Use of Water	-----		\$
			\$
			\$
			\$
			\$
			\$

St. Davis  
 Rk  
 Ave. No. 31

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report 1912

---

..... Main

Gate at ●

Elev. of Main at tap .....

● Gate at

---

● Curb Box

RENEWAL TAP 1929