

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$ "	\$
	Lead		
1	Curb	} Cock Valve } $\frac{3}{4}$ " in.	\$
			T.S. & V.
1	Service box	} Short $3\frac{1}{2}$ x $4\frac{1}{2}$ }	\$
	Old returned		Long $4\frac{1}{2}$ x $5\frac{1}{2}$ }
25	Ft. $\frac{3}{4}$ in.	} Copper } Pipe at	\$
			Gal. } C.P.
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	Coupl'gs. to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

DAVIS

St. No. 6

Name of Owner

McCARTHY

Labor and Mat'l. Report

OCT 22 1986



28 1/2" 13-0"

● Curb Box

4" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD TAP SHOT OFF