

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$ "	\$
1	Curb		\$
		} Cock Valve T.S. & V. $\frac{3}{4}$ " in.	\$
1	Service box Old returned		{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ }
12	Ft. $\frac{3}{4}$ in.	{ Copper C.I. C.I. } Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g } Coupl'gs	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor—	at	\$
	Hrs. Compressor at		\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. ELIZABETH
 Ave. No. 10
 Name of Owner _____

Labor and Mat'l. Report Apr. 24 1926



THIS TIE → 19' 15" 15' 15"
 MAY BE FROM
 PORCH CAN.

● Curb Box

6" Main Elev. of Main at tap 5'
 Gate at ● Gate at ●

● Curb Box

- OLD LEAD TO BE DUG UP

- BUFFALO BOX DEAD