

### LABOR AND MATERIALS

Copper Lead	} Connection	$\frac{1}{2}$ "		\$
1 Curb	{ Cock Valve T.S.&V.	$\frac{3}{4}$ "	in.	\$
1 Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 6\frac{1}{2}$ Buffer Rdway			\$
26 Ft.	$\frac{3}{4}$ in.	{ Copper Galv Iron Cast Iron	} Pipe at	\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g Inc'g	{ Couplings	to in. at	\$
	Union		in. at	\$
	Meter		in. at	\$
	Lead Joints at			\$
	Leadite Joints at			\$
	Hrs. Foreman at			\$
	Hrs. Chauffeur at			\$
	Hrs. Tapper at			\$
	Hrs. Labor at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
				\$
				\$
				\$
				\$
				\$
				\$

St. \_\_\_\_\_  
 Pt. \_\_\_\_\_  
 Ave. No. 7

Elizabeth

---

Name of Owner  
INSTALLED OCT. 1922

---

SEP 6 - 1939

Labor and Mat'l. Report 19

---

● Curb Box

---

6" Main Elev. of  
Main at tap

---

Gate at ● ● Gate at

---

● Curb Box