

LABOR AND MATERIALS

1	Copper Lead	} Connection	$\frac{1}{2}$ "	\$
1	Curb		} Cock Valve P.S. & V.	$\frac{3}{4}$ " in.
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$		
12 Ft.	$\frac{3}{4}$ in.		} Copper G.I. Gal.	Pipe at
	Nipples	in. at		\$
	Bushings	to in. at	\$	
	Red'g Inc'g	} Coupl'gs	to in. at	\$
	Union		in. at	\$
	Meter	in. at	\$	
	Compound Joints at	\$		
	Maintenance Foreman	\$		
	Hrs. Water Maint. Man—1 at	\$		
	Hrs. Water Maint. Man—2 at	\$		
	Hrs. Garage Foreman at	\$		
	Hrs. Labor— at	\$		
	Hrs. Compressor at	\$		
	Trucking	\$		
	Pav't Patch	\$		
		\$		
		\$		
		\$		
		\$		
		\$		

St. ELIZABETH Ave. No. 8

Name of Owner _____

Labor and Mat'l. Report APR. 25 1923

18'-5" 5'-6"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● Gate at

12' to MAIN

● Curb Box

$\frac{1}{2}$ LEAD
LSM-5C-6-1-67