

### LABOR AND MATERIALS

1	Copper	}	Connection	$\frac{3}{4}$ "		\$
	Lead	}				
1	Curb	}	Cock Valve	$\frac{3}{4}$ "		\$
		}	T. S. & V.			
1	Service box	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$			
	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$			
			Buff or Rdway			\$
11	Ft.	}	Copper			
	$\frac{3}{4}$ "		G. I.	Pipe at		
			C. I.			
	Nipples		in. at			\$
	Bushings		to in. at			\$
	Red'g	}	Coupl'gs	to in. at		\$
	Inc'g					
	Union		in. at			\$
	Meter		in. at			\$
	Lead Joints at					\$
	Compound Joints at					\$
	Maintenance Foreman					\$
	Hrs. Water Maint. Man-1 at					\$
	Hrs. Water Maint. Man-2 at					\$
	Hrs. Garage Foreman at					\$
	Hrs. Labor at					\$
	Hrs. Compressor at					\$
	Compensation Ins. at \$		per C			\$
	Trucking					\$
	Pav't Patch					\$
	Tap by G. S. GORD					\$
	+ Cal. 6-22-59					\$
	O'head					\$

~~St.~~  
~~Pl.~~  
 Ave. No. 2

Empire

Name of Owner  
Garrett Shine

Labor and Mat'l. Report June 22 19 59

33' 10"

26' 5"

● Curb Box

6" Main
Elev. of Main at tap 5'

Gate at ●
● Gate at

● Curb Box

LSM-SC-2-5 56