

LABOR AND MATERIALS

1	Copper Lead	{ Connection $\frac{3}{4}$ "		\$ 2.29
1	Curb	{ Cock Valve T.S. & V. } $\frac{3}{4}$ in.		\$ 2.70
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway }		\$ 4.25
11	Ft. $\frac{3}{4}$ in.	{ Copper C.I. C.I. } Pipe at 35		\$ 3.85
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g Inc'g	{ Coupl'gs to in. at	\$	
	Union	in. at	\$	
	Meter	in. at	\$	
	Lead Joints	at	\$	
	Compound Joints	at	\$	
2	Hrs. Water Maint. Man-1	at	\$	2.24
4	Hrs. Water Maint. Man-2	at	\$	4.08
11	Hrs. Labor	at	\$	10.01
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins. at \$	per C.	\$	36
	Trucking		\$	1.00
	Pav't Patch	B.P.	\$	
	O'head		\$	
			\$	30.78

167 1950 Before Taring

St. First
 Pl. 66
 Ave. No. 66

Name of Owner Mora Fontaine

Labor and Mat'l. Report July 20 1950

RAZED
1998

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

LSM-5C 10-21-49