

LABOR AND MATERIALS

Copper	} Connection	-----	\$	-----						
Lead										
Curb	{ Cock Valve T. S. & V. }	} -----	in.	-----	\$					
Service Box										
Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }	} -----		-----	\$					
Ft.						} -----	in.	-----	\$	
	{ Copper Galv Iron Cast Iron }	} Pipe at	-----	-----	\$					
Nipples						-----	in.	at	-----	\$
Bushings						-----	to	-----	in.	at
Rad'g Inc'g	} Couplings	} -----	to	-----	in.	at	-----	\$		
Union									-----	in.
Meter	-----	in.	at	-----	\$					
Lead Joints	at	-----	\$							
Leadite Joints	at	-----	\$							
Hrs. Foreman	at	-----	\$							
Hrs. Chauffeur	at	-----	\$							
Hrs. Tapper	at	-----	\$							
Hrs. Labor	at	-----	\$							
Hrs. Labor	at	-----	\$							
Hrs. Compressor	at	-----	\$							
Compensation Ins.	-----	\$								
Trucking	-----	\$								
Builders Use of Water	-----	\$								
	-----	\$								
	-----	\$								
	-----	\$								
	-----	\$								
	-----	\$								
	-----	\$								

St.
Pt: Pt. Amherst Rd Ave. No. 43

Name of Owner
J.F. Segerson

Labor and Mat'l. Report 7-18-39 19



Main Elev. of
Main at tap

Gate at ● ● Gate at

● Curb Box