

Labor and Materials

1	Copper	} Connection $\frac{1}{2}$ "		\$
	Lead			
1	Curb	} Cock Valve T-S. & V. $\frac{5}{8}$ in		\$
1	Service Box		} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway	
	Old-retained			
9	Ft. $\frac{3}{4}$ in.	} Copper Galv Iron Cast Iron		Pipe at
	Nipples		in. at	\$
	Bushings	to	in. at	\$
	Red'g	} Couplings	to	in. at
	Inc'g			\$
	Union	in. at	\$	
	Meter	in. at	\$	
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
	Hrs. Foreman	at	\$	
	Hrs. Chauffeur	at	\$	
	Hrs. Tapper	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins.		\$	
	Trucking		\$	
	Builders Use of Water		\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. *South*
Pt. *South*
Ave. No. *39*

Name of Owner
Benj. D. Seville

Labor and Mat'l. Report *Apr. 10* 1917

25-5
26-6
● Curb Box

6" Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box.