

LABOR AND MATERIALS

1	Copper Lage	} Connection $\frac{3}{4}$	\$	_____
1	Curb Valve 1.5-8-4		} $\frac{3}{4}$ in.	\$
1	Service box Old returned	{ Short 3-1/2 x 4-1/2 Long 4-1/2 x 5-1/2 }		\$
9	Ft. $\frac{3}{4}$ in.	{ Copper Pipe	\$	_____
_____	Nipples	_____ in. at	\$	_____
_____	Bushings	_____ to _____ in. at	\$	_____
_____	Red'g			
_____	Inc'g			
_____	Union	_____ in. at	\$	_____
_____	Meter	_____ in. at	\$	_____
_____			\$	_____
_____	Compound Joints at		\$	_____
_____	Maintenance Foreman		\$	_____
_____	Hrs. Water Maint. Man - 1 at		\$	_____
_____	Hrs. Water Maint. Man - 2 at		\$	_____
_____	Hrs. Garage Foreman	_____ at	\$	_____
_____	Hrs. Labor	_____ at	\$	_____
_____	Hrs. Compressor at		\$	_____
_____			\$	_____
_____	Trucking		\$	_____
_____	Pav't Patch		\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____

St. FOURTH
 No. 9
 Name of Owner _____

Labor and Mat'l. Report 1934, OCT. 16



19-9 20-6

● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

9' to main

3/4" Copper ● Curb Box

OLD SHUT OFF AT MAIN

PENOR

TAX ID# 309.12-13-28