

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} Cock } Valve } T. S. & V.	in.	\$	
Service box		} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2		
Old returned				\$
44 Ft.	} Copper } C.I. } C.I.	3/4 in.	Pipe at \$	
Nipples		in.	at \$	
Bushings		to in.	at \$	
Red'g	} Coupl'gs	to in.	at \$	
Inc'g				
Union	in.	at \$		
Meter	in.	at \$		
Compound Joints	at \$			
Maintenance Foreman	\$			
Hrs. Water Maint. Man—1	at \$			
Hrs. Water Maint. Man—2	at \$			
Hrs. Garage Foreman	at \$			
Hrs. Labor—	at \$			
Hrs. Compressor	at \$			
Trucking	\$			
Pav't Patch	\$			
	\$			
	\$			
	\$			
	\$			
	\$			
	\$			

St. FRANKLIN
 Ave. No. 28
 Name of Owner _____
 TAX ID # 309.16-6-29

Labor and Mat'l. Report 1994

