

# LABOR AND MATERIALS

Copper } Connection 3/4 \$ \_\_\_\_\_  
 Lead }  
 Curb } Cock } \_\_\_\_\_ in. \$ \_\_\_\_\_  
 } Valve }  
 } T.S. & V. }  
 Service box { Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_  
 Old returned { Long 4-1/2 x 5-1/2 } \$ \_\_\_\_\_  
40 Ft. 9 in. { Copper } Pipe at \$ \_\_\_\_\_  
 } G.I. }  
 } C.I. }  
 \_\_\_\_\_ Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Red'g \_\_\_\_\_  
 \_\_\_\_\_ Inc'g \_\_\_\_\_  
 \_\_\_\_\_ Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ Compound Joints at \$ \_\_\_\_\_  
 \_\_\_\_\_ Maintenance Foreman \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 \_\_\_\_\_ Hrs. Compressor at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ Trucking \$ \_\_\_\_\_  
 \_\_\_\_\_ Pav't Patch \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

34 Feet  
Sewer MAIN

Franklin

St.  
Pl. Ave. No. 38

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report 2006

● Curb Box

6"

Main

Elev. of Main at tap 5'3"

Gate at ●

● Gate at

● Curb Box