

### Labor and Materials

1	Copper Lead	Connection	$\frac{1}{2}$			\$
1	Curb	Cock Valve	$\frac{3}{8}$	in		\$
1	Service Box	}	Short	3 1/2 x 4 1/2		\$
	Old returned		Long	4 1/2 x 5 1/2		\$
8	Ft.	3/4 in.			Pipe at	\$
						\$
	Nipples	in. at				\$
	Bushings	to		in. at		\$
	Red'g Inc'g	Complings	to		in. at	\$
	Union	in. at				\$
	Meter	in. at				\$
	Lead Joints	at				\$
	Leadite Joints	at				\$
	Hrs. Foreman	at				\$
	Hrs. Chauffeur	at				\$
	Hrs. Tapper	at				\$
	Hrs. Labor	at				\$
	Hrs. Labor	at				\$
	Hrs. Compressor	at				\$
	Compensation Ins.					\$
	Trucking					\$
	Builders Use of Water					\$
						\$
						\$
						\$
						\$
						\$
						\$

FREDELLA      ~~St~~ 22-224  
Ave. No. 512

---

Name of Owner     *Geo. J. Fredella*    

---

Labor and Mat'l. Report     10/15/20     19

---

---

6" Main
Elev. of Main at tap     4    

---

Gate at ● ● Gate at

---

● Curb Box