

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"	\$	_____		
1	Curb			Cock Valve T.S. & V.	} SAME	in.	\$
	Service box Old returned	{	Short 3-1/2 x 4-1/2	}			\$
			Long 4-1/2 x 5-1/2		\$	_____	
6	Ft.	{	3/4 in.	} Copper ad. cont.	Pipe at	\$	_____
							\$
	Nipples			in. at	\$	_____	
	Bushings			to _____ in. at	\$	_____	
	Red'g				\$	_____	
	Inc'g				\$	_____	
	Union			in. at	\$	_____	
	Meter			in. at	\$	_____	
					\$	_____	
	Compound Joints at				\$	_____	
	Maintenance Foreman				\$	_____	
	Hrs. Water Maint. Man - 1 at				\$	_____	
	Hrs. Water Maint. Man - 2 at				\$	_____	
	Hrs. Garage Foreman			at	\$	_____	
	Hrs. Labor			at	\$	_____	
	Hrs. Compressor at				\$	_____	
					\$	_____	
	Trucking				\$	_____	
	Pav't Patch				\$	_____	
					\$	_____	
					\$	_____	
					\$	_____	
					\$	_____	
					\$	_____	

FREDELLA ~~St.~~
~~Pt.~~ Ave. No. 10

Name of Owner
ROBERT N. LANCE

Labor and Mat'l. Report 19 71, SEPT. 22



25'-9" 41'-6"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box