

LABOR AND MATERIALS

1	Copper } Connection $\frac{3}{4}$	\$	
1	Lead } Cock		
1	Curb } Valve		
	J.G. & V. } in.	\$	
1	Service box { Short 3-1/2 x 4-1/2	\$	
	Old returned { Long 4-1/2 x 5-1/2	\$	
8	Ft. $\frac{3}{4}$ in. { Copper		
	Gal. } Pipe at	\$	
	Nipples _____ in. at	\$	
	Bushings _____ to _____ in. at	\$	
	Red'g _____		
	Inc'g _____		
	Union _____ in. at	\$	
	Meter _____ in. at	\$	
	_____	\$	
	Compound Joints at	\$	
	Maintenance Foreman _____	\$	
	Hrs. Water Maint. Man - 1 at	\$	
	Hrs. Water Maint. Man - 2 at	\$	
	Hrs. Garage Foreman _____ at	\$	
	Hrs. Labor _____ at	\$	
	Hrs. Compressor at	\$	
	_____	\$	
	Trucking _____	\$	
	Pav't Patch _____	\$	
	_____	\$	
	_____	\$	
	_____	\$	
	_____	\$	
	_____	\$	
	_____	\$	

FULTON

St. Ave. No. 36

Name of Owner _____

Labor and Mat'l. Report 1929, JUNE 13



29'4" 22'

● Curb Box

10" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD TAP DISCONNECTED