

LABOR AND MATERIALS

_____ Copper } Connection _____ \$ _____
 _____ Lead }
 _____ Curb } Cock _____ in. _____ \$ _____
 _____ Valve }
 _____ T.S. & V. }
 _____ Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____
 _____ Old returned { Long 4-1/2 x 5-1/2 }
 _____ Ft. _____ in. { Copper } Pipe at _____ \$ _____
 _____ { G.I. }
 _____ { C.I. }
 _____ Nipples _____ in. at _____ \$ _____
 _____ Bushings _____ to _____ in. at _____ \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$ _____
 _____ Meter _____ in. at _____ \$ _____
 _____ \$ _____
 _____ Compound Joints at _____ \$ _____
 _____ Maintenance Foreman _____ \$ _____
 _____ Hrs. Water Maint. Man - 1 at _____ \$ _____
 _____ Hrs. Water, Maint. Man - 2 at _____ \$ _____
 _____ Hrs. Garage Foreman _____ at _____ \$ _____
 _____ Hrs. Labor _____ at _____ \$ _____
 _____ Hrs. Compressor at _____ \$ _____
 _____ \$ _____
 _____ Trucking _____ \$ _____
 _____ Pav't Patch _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____

129 Glen

St.
Pl. Ave. No. 178

Name of Owner _____

Labor and Mat'l. Report 10-12/12/16

● Curb Box

12' Main

Elev. of Main at tap 7'

Gate at ●

● Gate at

● Curb Box

Replaced
 15 Feet of 1" To Plastic
 in middle of the service
 There is a 1" curb stop 2 FT
 off the main

REPLACED 15 FEET OF 1" COPPER W/
1" PLASTIC IN MIDDLE OF THE SERVICE.

THERE IS A 1" CURB STOP 2 FT OFF THE
MAIN WITH A CURB BOX 4" UNDER THE PAVEMENT
IN ROAD

TE:

Glen 128

COMPLETED

TIME:

Glen ST 128

* THERE IS A SECOND CURB STOP 3 FEET OFF THE
CURB (LEFT IN ON POSITION) THEN A 3RD ONE IN
THE SIDEWALK USED TO TURN WATER ON AND OFF
TO BUILDING