

LABOR AND MATERIALS

_____	Copper } Connection	<u>3/4</u>	_____	\$ _____
_____	Lead } Cock			
_____	Curb } Valve	<u>3/4</u> in.	_____	\$ _____
		T.S. & V. }		
<u>1</u>	Service box	{ Short 3-1/2 x 4-1/2	_____	\$ _____
	Old returned	{ Long 4-1/2 x 5-1/2 }	_____	\$ _____
<u>15</u>	Ft. <u>3/4</u> in. { Copper		Pipe at _____	\$ _____
		{ Gal. }		
		{ Gal. }		
_____	Nipples _____	in. at _____	_____	\$ _____
_____	Bushings _____	to _____ in. at _____	_____	\$ _____
_____	Red'g _____			\$ _____
_____	Inc'g _____			\$ _____
_____	Union _____	in. at _____	_____	\$ _____
_____	Meter _____	in. at _____	_____	\$ _____
_____	_____			\$ _____
_____	Compound Joints at _____		_____	\$ _____
_____	Maintenance Foreman _____		_____	\$ _____
_____	Hrs. Water Maint. Man - 1 at _____		_____	\$ _____
_____	Hrs. Water Maint. Man - 2 at _____		_____	\$ _____
_____	Hrs. Garage Foreman _____	at _____	_____	\$ _____
_____	Hrs. Labor _____	at _____	_____	\$ _____
_____	Hrs. Compressor at _____		_____	\$ _____
_____	_____			\$ _____
_____	Trucking _____		_____	\$ _____
_____	Pav't Patch _____		_____	\$ _____
_____	_____			\$ _____
_____	_____			\$ _____
_____	_____			\$ _____
_____	_____			\$ _____
_____	_____			\$ _____
_____	_____			\$ _____

GLEN

St. _____
 Ass. No. 299-303

Name of Owner
CHURCH OF MESSIAH

Labor and Mat'l. Report 1934, AUG. 17



21'4" 59'0

● Curb Box

12" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

OLD SHUT OFF AT MAIN